

Location	Comment
401007	Old style township.
401011	Old style township.
401072	Survey data may not be shown on official plan or may be incorrect.
401076	Survey data may not be shown on official plan or may be incorrect.
401088	Survey data may not be shown on official plan or may be incorrect.
401092	Survey data may not be shown on official plan or may be incorrect.
401095	Survey data may not be shown on official plan or may be incorrect.
401096	Survey data may not be shown on official plan or may be incorrect.
401097	Survey data may not be shown on official plan or may be incorrect.
401098	Survey data may not be shown on official plan or may be incorrect.
402008	Township plans within existing or former forest reserve areas may not show all surveyed sections.
402042	Possible descriptive problem with the witness monument at NE 11.
402072	Survey data may not be shown on official plan or may be incorrect.
402076	Survey data may not be shown on official plan or may be incorrect.
402088	Survey data may not be shown on official plan or may be incorrect.
402092	Survey data may not be shown on official plan or may be incorrect.
403002	Description of monuments affecting N boundary of section 34 may be incorrect.
403003	Description of monuments affecting the N boundary of section 34-T2-R3-W4M may be incorrect.
403008	Township plans within existing or former forest reserve areas may not show all surveyed sections.
403011	Old style township.
403020	Old style township.
403072	Survey data may not be shown on official plan or may be incorrect.
403076	Survey data may not be shown on official plan or may be incorrect.
403088	Survey data may not be shown on official plan or may be incorrect.
403092	Survey data may not be shown on official plan or may be incorrect.
404008	Possible descriptive problem with the witness monument at NE 35.
404009	Possible descriptive problem with the witness monument at NE 35-T8-R4-W4M.
404039	Lakes plotted in wrong location.
404044	Possible descriptive problem with the witness monument at NE 8.
404065	Possible descriptive problem with the witness monument at NE 36-T65-R5-W4M.
404066	Possible descriptive problem with the witness monument at NE 36-T65-R5-W4M.
404072	Survey data may not be shown on official plan or may be incorrect.
404076	Survey data may not be shown on official plan or may be incorrect.
404088	Survey data may not be shown on official plan or may be incorrect.
404092	Survey data may not be shown on official plan or may be incorrect.

Location	Comment
405065	Possible descriptive problem with the witness monument at NE 36.
405066	Possible descriptive problem with the witness monument at NE 36-T65-R5-W4M. Description of monuments affecting sections 6 & 7 may be incorrect. Letter on file regarding sections 3 & 4.
405072	Survey data may not be shown on official plan or may be incorrect.
405076	Survey data may not be shown on official plan or may be incorrect.
405088	Survey data may not be shown on official plan or may be incorrect.
406042	Township plans within existing or former forest reserve areas may not show all surveyed sections.
406043	Township plans within existing or former forest reserve areas may not show all surveyed sections.
406059	Possible descriptive problem with the witness monument in section 1-T59-R7-W4M.
406066	Description of monuments affecting sections 1 & 12 may be incorrect.
406076	Survey data may not be shown on official plan or may be incorrect.
406079	Description of monuments affecting sections 5-8, 17-20, 29-32 may be incorrect.
406080	Description of monuments affecting sections 4-6 may be incorrect.
406082	Description of monuments affecting sections 1-36 may be incorrect.
407012	Possible descriptive problem with the witness monument at NE 19.
407044	Township plans within existing or former forest reserve areas may not show all surveyed sections.
407059	Possible descriptive problem with the witness monument in section 1.
407063	Wit. Mon. at NE 6 found 5 S instead of 3 S.
407078	Description of monuments affecting sections 19, 20, 29-36 may be incorrect.
407079	Description of monuments affecting sections 1-7, 10-15, 18, 19, 22-27, 30, 36 may be incorrect.
407080	Possible descriptive problem with the witness monument at NE 33.
408010	Old style township.
408043	Township plans within existing or former forest reserve areas may not show all surveyed sections.
409014	Old style township.
409021	Distance on the north boundary of section 35 may be in error.
409022	Distance affecting south boundary of sections 2 & 3 may be incorrect.
411021	Possible descriptive problem with the witness monument at E1/4-10.
411050	Possible descriptive problem with the witness monument at NE14.
412013	Old style township.
412021	Possible descriptive problem with the witness monument in section 2.
412023	Old style township.
412045	Distance affecting west boundary of section 30 may be incorrect. Description of monuments affecting section 30 may be incorrect.
413013	Old style township.
413018	Old style township.

Location	Comment
413020	Old style township.
413021	Old style township.
413022	Old style township.
413026	Old style township.
413045	Description of monuments affecting section 25 may be incorrect.
413049	Old style township.
413051	Description of monuments affecting section 4 may be incorrect.
413066	Possible problem with the witness monument at NE35.
413088	Survey data may not be shown on official plan or may be incorrect.
414011	Possible descriptive problem with the witness monument at NE14.
414014	Old style township.
414020	Old style township.
414021	Old style township.
414022	Old style township.
414023	Old style township.
414024	Old style township.
414025	Old style township.
414026	Old style township.
414049	Old style township.
414051	Old style township.
414054	Old style township.
414055	Old style township.
414058	Description of monuments affecting section 1 may be incorrect.
414060	Bearing affecting east boundary of sections 1, 12, 13, 24, 25, 36 may be incorrect.
414065	Bearing affecting east boundary of section 14 may be incorrect.
414088	Survey data may not be shown on official plan or may be incorrect.
415005	Old style township.
415012	Old style township.
415014	Old style township.
415020	Old style township.
415021	Old style township.
415022	Old style township.
415023	Old style township.
415024	Old style township.
415025	Old style township.
415043	Old style township.
415050	Old style township.
415051	Old style township.
415053	Old style township.
415088	Survey data may not be shown on official plan or may be incorrect.

Location	Comment
416003	Old style township.
416005	Old style township.
416008	Official restoration surveys restoring some monuments between 1953 & 1962 may not have been incorporated into existing township plan.
416009	Official restoration surveys restoring some monuments between 1953 & 1962 may not have been incorporated into existing township plan.
416011	Distance affecting east boundary of section 2 may be incorrect. Description of monuments along south boundary of the township may be incorrect.
416020	Old style township.
416021	Old style township.
416022	Old style township.
416023	Old style township.
416024	Old style township.
416025	Old style township.
416050	Old style township.
416057	Old style township.
416059	Bearing affecting east boundary of section 4 may be incorrect.
416068	Distance affecting NE boundary of lot 4 may be incorrect.
416088	Survey data may not be shown on official plan or may be incorrect.
417003	Old style township.
417004	Old style township.
417012	Old style township.
417020	Old style township.
417021	Old style township.
417022	Old style township.
417023	Old style township.
417024	Old style township.
417025	Old style township.
417040	Old style township.
417044	Old style township.
417081	Possible monument changes on the east boundary of the township.
417083	Possible descriptive problem with the witness monument at NE33.
417084	Possible descriptive problem with the witness monument at NE33-83-17-4.
417088	Survey data may not be shown on official plan or may be incorrect.
418004	Old style township.
418005	Old style township.
418006	Old style township.
418007	Old style township.
418012	Old style township.
418015	Old style township.

Location	Comment
418020	Old style township.
418021	Old style township.
418022	Old style township.
418023	Old style township.
418024	Old style township.
418025	Old style township.
418026	Old style township.
418039	Old style township.
418040	Old style township.
418041	Old style township.
418042	Old style township.
418049	Description of monuments affecting sections 18 & 19 may be incorrect.
418050	Possible descriptive problem with the witness monument at E 1/4 35.
418088	Survey data may not be shown on official plan or may be incorrect.
419003	Old style township.
419004	Old style township.
419005	Old style township.
419008	Old style township.
419014	Old style township.
419015	Old style township.
419016	Old style township.
419021	Old style township.
419022	Old style township.
419023	Old style township.
419024	Old style township.
419025	Old style township.
419026	Old style township.
419040	Old style township.
419041	Old style township.
419042	Old style township.
419046	Bearing affecting north boundary of section 20 may be incorrect.
419049	Description of monuments affecting sections 13 & 24 may be incorrect.
419052	Township plans within existing or former forest reserve areas may not show all surveyed sections.
419054	Township plans within existing or former forest reserve areas may not show all surveyed sections.
419088	Survey data may not be shown on official plan or may be incorrect.
420003	Old style township.
420005	Old style township.
420015	Old style township.

Location	Comment
420021	Old style township.
420022	Old style township.
420023	Old style township.
420024	Old style township.
420026	Old style township.
420034	Distances affecting the south boundary of section 3 may be in error.
420035	Old style township.
420036	Old style township.
420042	Old style township.
420043	Old style township.
420052	Township plans within existing or former forest reserve areas may not show all surveyed sections.
420054	Township plans within existing or former forest reserve areas may not show all surveyed sections.
420088	Survey data may not be shown on official plan or may be incorrect.
421003	Old style township.
421004	Old style township.
421005	Old style township.
421016	Old style township.
421021	Old style township.
421022	Old style township.
421023	Old style township.
421024	Old style township.
421025	Old style township.
421026	Old style township.
421027	Old style township.
421028	Old style township.
421088	Survey data may not be shown on official plan or may be incorrect.
422003	Old style township.
422004	Old style township.
422005	Old style township.
422007	Old style township.
422013	Old style township.
422022	Old style township.
422023	Old style township.
422024	Old style township.
422025	Old style township.
422026	Old style township.
422027	Old style township.
422028	Old style township.

Location	Comment
422044	Old style township.
422088	Survey data may not be shown on official plan or may be incorrect.
423002	Old style township.
423003	Old style township.
423004	Old style township.
423005	Old style township.
423022	Old style township.
423023	Old style township.
423024	Old style township.
423025	Old style township.
423026	Old style township.
423027	Old style township.
423028	Old style township.
423033	Old style township.
423056	Description of monument affecting E 1/4 3 may be incorrect.
423088	Survey data may not be shown on official plan or may be incorrect.
424001	Old style township.
424003	Old style township.
424004	Old style township.
424005	Old style township.
424020	Bearing affecting east boundary of section 3 may be incorrect.
424022	Old style township.
424023	Possible descriptive problem with the witness monument at NE32.
424025	Old style township.
424026	Old style township.
424027	Old style township.
424028	Old style township.
424034	Old style township.
424039	Old style township.
424041	Old style township.
424058	Old style township.
424059	Old style township.
424066	Possible descriptive problem with the witness monument on north boundary of lot 1.
424084	Official restoration surveys affecting sections 31-36 may not have been incorporated into existing township plan.
424088	Survey data may not be shown on official plan or may be incorrect.
425001	Old style township.
425003	Distance affecting east boundary of section 1 may be incorrect. Old style township.
425004	Old style township.

Location	Comment
425007	Old style township.
425011	Old style township.
425023	Old style township.
425025	Old style township.
425026	Old style township.
425027	Old style township.
425028	Old style township.
425033	Old style township.
425034	Old style township.
425038	Old style township.
425039	Old style township.
425040	Old style township.
425042	Old style township.
425052	Road allowance adjacent to section 9 may be incorrectly shown. Old style township.
425058	Old style township.
425059	Old style township.
425084	Official restoration surveys affecting sections 31-36 may not have been incorporated into existing township plan.
425088	Survey data may not be shown on official plan or may be incorrect.
426003	Old style township.
426005	Old style township.
426006	Old style township.
426022	Old style township.
426023	Old style township.
426024	Old style township.
426025	Old style township.
426026	Old style township.
426028	Old style township.
426033	Old style township.
426034	Old style township.
426035	Old style township.
426037	Old style township.
426039	Old style township.
426049	Old style township.
426052	Old style township.
426053	Distance and bearing affecting north boundary of section 31 may be incorrect.
426054	Distance and bearing affecting south boundary of section 6 may be incorrect.
426059	Old style township.
426060	Old style township.



Location	Comment
426073	Township plans within existing or former forest reserve areas may not show all surveyed sections.
426084	Official restoration surveys affecting sections 35 & 36 may not have been incorporated into existing township plan.
426088	Survey data may not be shown on official plan or may be incorrect.
427023	Old style township.
427024	Old style township.
427025	Old style township.
427026	Old style township.
427027	Old style township.
427028	Old style township.
427033	Old style township.
427035	Old style township.
427041	Old style township.
427042	Old style township.
427046	Old style township.
427048	Area in SE section 7 may be incorrect. Old style township.
427049	Old style township.
427053	Road allowance adjacent to section 24 may be incorrectly shown.
427054	Description of monuments affecting sections 5 & 8 may be incorrect.
427055	Distance affecting NORTH boundary of section 7 may be incorrect.
427065	Bearing affecting west boundary of sections 3, 10, 15, 22, 27, 34 may be incorrect.
428003	Possible descriptive problem with the witness monument at NE34.
428004	Possible descriptive problem with the witness monument at NE 34-T3-R28-W4M.
428007	Old style township.
428010	Old style township.
428014	Old style township.
428023	Old style township.
428024	Old style township.
428025	Old style township.
428026	Old style township.
428027	Distance affecting west boundary of section 6 may be incorrect. Old style township.
428028	Old style township.
428031	Possible descriptive problem with the witness monument at S 1/4 2.
428033	Old style township.
428037	Distance affecting north boundary of section 31-T36-R28-W4M may be incorrect.
428038	Bearing affecting north boundary of section 32 may be incorrect.
428041	Unsurveyed north boundary of west colum of sections appears to be incorrectly drafted.

Location	Comment
428046	Old style township.
428048	Old style township.
429001	Township plans within existing or former forest reserve areas may not show all surveyed sections.
429004	Old style township.
429006	Old style township.
429009	Official restoration surveys affecting sections 31-34 may not have been incorporated into existing township plan.
429010	Official restoration surveys affecting sections 3-10 may not have been incorporated into existing township plan.
429015	Old style township.
429020	Several older surveys may not be noted on the current township plan.
429024	Old style township.
429025	Old style township.
429026	Old style township.
429027	Distance affecting east boundary of section 1 may be incorrect. Old style township.
429028	Old style township.
429029	Old style township.
429033	Old style township.
429034	Distance affecting east boundary of section 2 may be incorrect. Old style township.
430009	Official restoration surveys affecting sections 21-28, 36 may not have been incorporated into existing township plan.
430010	Official restoration surveys affecting sections 1 & 12 may not have been incorporated into existing township plan.
430015	Old style township.
501004	Township plans within existing or former forest reserve areas may not show all surveyed sections.
501007	Monument, distance and bearing affecting sections 1, 12, 13, 24, 25 may be incorrect.
501020	Distances and bearings may be in error along the 5th meridian.
501022	Old style township.
501024	Old style township.
501027	Possible descriptive problem with the witness monument at NE 35.
501028	Possible descriptive problem with the witness monument at NE 35-T27-R1-W5M.
501031	Distance affecting east boundary of sections 13 & 24 may be incorrect.
501033	Old style township.
501034	Old style township.
501037	Old style township.
501046	Old style township.

Location	Comment
501053	Bearing affecting north boundary of sections 31-33 may be incorrect. Description of monuments affecting the west boundary of sections 6, 7, 18, 19, 30, 31 may be incorrect.
501070	Township plans within existing or former forest reserve areas may not show all surveyed sections.
501071	Township plans within existing or former forest reserve areas may not show all surveyed sections.
501073	Township plans within existing or former forest reserve areas may not show all surveyed sections.
501084	Official restoration surveys restoring some monuments between 1953 & 1962 may not have been incorporated into existing township plan.
502011	Official restoration surveys restoring some monuments between 1953 & 1962 may not have been incorporated into existing township plan.
502012	Distance affecting east boundary of section 25 may be incorrect. Official restoration surveys restoring some monuments between 1953 & 1962 may not have been incorporated into existing township plan.
502013	Official restoration surveys affecting sections 1-2, 11-14, 23-26, 35-36 may not have been incorporated into existing township plan.
502019	Old style township.
502021	Old style township.
502033	Old style township.
502034	Old style township.
502036	Old style township.
502037	Old style township.
502038	Old style township.
502039	Old style township.
502040	Old style township.
502041	Old style township.
502042	Old style township.
502044	Old style township.
502045	Old style township.
502049	Possible descriptive problem with the witness monument at NE 17.
502070	Township plans within existing or former forest reserve areas may not show all surveyed sections.
502073	Township plans within existing or former forest reserve areas may not show all surveyed sections.
502074	Township plans within existing or former forest reserve areas may not show all surveyed sections.
502080	Distance affecting north boundary of section 34 may be incorrect.
502084	Official restoration surveys restoring some monuments between 1953 & 1962 may not have been incorporated into existing township plan.

Location	Comment
503009	Official restoration surveys restoring some monuments between 1953 & 1962 may not have been incorporated into existing township plan.
503010	Official restoration surveys affecting sections 34-36 may not have been incorporated into existing township plan.
503011	Official restoration surveys affecting sections 1-3, 12 may not have been incorporated into existing township plan.
503015	Township plans within existing or former forest reserve areas may not show all surveyed sections.
503016	Township plans within existing or former forest reserve areas may not show all surveyed sections.
503021	Hydrographic error affecting sections 1-6. Old style township.
503022	Old style township.
503024	Old style township.
503036	Old style township.
503037	Old style township.
503038	Old style township.
503039	Old style township.
503040	Old style township.
503041	Old style township.
503042	Old style township.
503043	Old style township.
503045	Distance affecting sections 20, 29, 31, 32 may be incorrect.
503056	Distance affecting north boundary of section 34 may be incorrect.
503067	Township plans within existing or former forest reserve areas may not show all surveyed sections.
503074	Township plans within existing or former forest reserve areas may not show all surveyed sections.
503084	Official restoration surveys restoring some monuments between 1953 & 1962 may not have been incorporated into existing township plan.
504016	Township plans within existing or former forest reserve areas may not show all surveyed sections.
504018	Township plans within existing or former forest reserve areas may not show all surveyed sections.
504030	Old style township.
504031	Bearing affecting north boundary of section 22 may be incorrect.
504035	Possible descriptive problem with the witness monument at NE 26.
504040	Old style township.
504041	Old style township.
504056	Description of monuments affecting section 6 may be incorrect.
504063	Possible descriptive problem with the witness monument at NE 8.

Location	Comment
504067	Township plans within existing or former forest reserve areas may not show all surveyed sections.
504074	Township plans within existing or former forest reserve areas may not show all surveyed sections.
504084	Official restoration surveys restoring some monuments between 1953 & 1962 may not have been incorporated into existing township plan.
505008	Official restoration surveys restoring some monuments between 1953 & 1962 may not have been incorporated into existing township plan.
505012	All unsurveyed theoretical road allowances are 99 feet wide.
505019	All unsurveyed theoretical road allowances are 99 feet wide.
505023	Township plans within existing or former forest reserve areas may not show all surveyed sections.
505024	Old style township.
505025	Old style township.
505026	Distance 40.17 affecting east boundary of section 36 should be 41.17.
505027	Old style township.
505035	Possible descriptive problem with the witness monument at NE 12.
505041	Description of monuments affecting section 13 may be incorrect.
505044	Bearings & Distances affecting north boundary of the township are superseded by surveys shown on the township plan to the north.
505045	Bearing affecting north boundary of section 36-T44-R5-W5M may be incorrect.
505056	Description of monuments affecting section 1 may be incorrect.
505061	Possible descriptive problem with the witness monument at NE 11.
505066	Township plans within existing or former forest reserve areas may not show all surveyed sections.
505072	Township plans within existing or former forest reserve areas may not show all surveyed sections.
505084	Official restoration surveys restoring some monuments between 1953 & 1962 may not have been incorporated into existing township plan.
506007	All unsurveyed theoretical road allowances are 99 feet wide.
506008	Official restoration surveys affecting sections 1-2, 11-13 may not have been incorporated into existing township plan. Check B.C. boundary report for distance discrepancy.
506020	All unsurveyed theoretical road allowances are 99 feet wide.
506072	Township plans within existing or former forest reserve areas may not show all surveyed sections.
506075	Township plans within existing or former forest reserve areas may not show all surveyed sections.
506076	Township plans within existing or former forest reserve areas may not show all surveyed sections.

Location	Comment
506084	Official restoration surveys affecting sections 31-36 may not have been incorporated into existing township plan.
507026	Description of monument affecting NE33 may be incorrect.
507036	Description of monuments affecting sections 16 & 17 may be incorrect.
507039	Descriptive problem with the witness monument at NE26.
507050	Possible descriptive problem with the witness monument at NE 7.
507051	Possible descriptive problem with the witness monument at NE 27.
507076	Official restoration surveys affecting sections 6, 7, 18, 19, 30, 31 may not have been incorporated into existing township plan.
507084	Official restoration surveys affecting sections 31-36 may not have been incorporated into existing township plan.
508024	Township plans within existing or former forest reserve areas may not show all surveyed sections.
508036	Official restoration surveys restoring some monuments between 1953 & 1962 may not have been incorporated into existing township plan.
508044	Official restoration surveys affecting monument at N 1/4-31 may not have been incorporated into existing township plan.
508045	Official restoration surveys affecting monument at N 1/4-31-T44-R8-W5M may not have been incorporated into existing township plan.
508073	Township plans within existing or former forest reserve areas may not show all surveyed sections.
508074	Description of monuments affecting section 4 may be incorrect.
508075	Official restoration surveys affecting sections 32 & 33 may not have been incorporated into existing township plan. Official restoration surveys restoring other monuments between 1953 & 1962 may not have been incorporated into existing township plan.
508076	Official restoration surveys affecting sections 1, 4, 5, 7-18, 20, 21, 24, 25, 28, 29, 31-36 may not have been incorporated into existing township plan.
508084	Official restoration surveys affecting sections 31-36 may not have been incorporated into existing township plan.
509024	All unsurveyed theoretical road allowances are 99 feet wide.
509037	Official restoration surveys restoring some monuments between 1953 & 1962 may not have been incorporated into existing township plan.
509039	Investigation survey affecting sections 3, 4, 10 and 15 show different monuments than is shown on the township plan.
509057	Description of monuments affecting sections 33-35 may be incorrect.
509061	Description of monuments affecting sections 10 & 11 may be incorrect.
509071	Township plans within existing or former forest reserve areas may not show all surveyed sections.
509076	Official restoration surveys affecting sections 1-23, 26-36 may not have been incorporated into existing township plan.

Location	Comment
509077	Official restoration surveys affecting sections 1-6 may not have been incorporated into existing township plan.
509084	Official restoration surveys affecting sections 31-36 may not have been incorporated into existing township plan.
510024	Possible descriptive problem with the witness monument at NE 19.
510054	Description of monuments affecting sections 7, 8, 17, 18 may be incorrect.
510076	Official restoration surveys affecting sections 1-6, 9-16, 23-36 may not have been incorporated into existing township plan.
510084	Official restoration surveys affecting sections 31-36 may not have been incorporated into existing township plan.
511039	Township plans within existing or former forest reserve areas may not show all surveyed sections.
511040	Township plans within existing or former forest reserve areas may not show all surveyed sections.
511075	Official restoration surveys restoring some monuments between 1953 & 1962 may not have been incorporated into existing township plan.
511076	Official restoration surveys affecting sections 1, 31-36 may not have been incorporated into existing township plan.
511084	Official restoration surveys affecting sections 31-36 may not have been incorporated into existing township plan.
512084	Official restoration surveys affecting sections 31-36 may not have been incorporated into existing township plan.
512108	Distance affecting south boundary of lot 9 range III may be incorrect.
512109	Boyer Settlement distance 90.9 should be 9.09.
513053	Official restoration surveys affecting sections 6, 7, 18 may not have been incorporated into existing township plan.
513055	Discrepancies on adjoining township plan boundaries affecting sections 30 & 31.
513084	Official restoration surveys affecting section 36 may not have been incorporated into existing township plan.
513109	Boyer Settlement distance 90.9 should be 9.09.
514052	Official restoration surveys affecting sections 6, 7, 18, 19, 30, 31-36 may not have been incorporated into existing township plan.
514053	Official restoration surveys affecting sections 1-14, 16-18, 25, 36, 30-36 may not have been incorporated into existing township plan.
514054	Official restoration surveys affecting sections 1-7 may not have been incorporated into existing township plan. Official restoration surveys restoring other monuments between 1953 & 1962 may not have been incorporated into existing township plan.
514055	Discrepancies on adjoining township plan boundaries affecting sections 25 & 36.
514084	Official restoration surveys affecting sections 31-35 may not have been incorporated into existing township plan.

Location	Comment
515051	Official restoration surveys affecting sections 31-36 may not have been incorporated into existing township plan. Official restoration surveys restoring other monuments between 1953 & 1962 may not have been incorporated into existing township plan.
515052	Official restoration surveys affecting sections 1-6, 9, 10, 12-16, 21-28, 32-36 may not have been incorporated into existing township plan.
515053	Official restoration surveys affecting sections 1-5, 11-14, 25, 34-36 may not have been incorporated into existing township plan.
515054	Official restoration surveys affecting sections 1, 12, 31-33 may not have been incorporated into existing township plan.
515055	Official restoration surveys affecting sections 4-6 may not have been incorporated into existing township plan.
515076	Bearing affecting north boundary of section 19 may be incorrect.
515084	Official restoration surveys affecting sections 32-34 may not have been incorporated into existing township plan.
515085	Official restoration surveys affecting sections 18, 19, 30, 31 may not have been incorporated into existing township plan.
515105	Bearing affecting east boundary of section 14 may be incorrect.
516051	Official restoration surveys affecting sections 19, 25, 35, 36 may not have been incorporated into existing township plan.
516052	Official restoration surveys affecting sections 1-4, 7-36 may not have been incorporated into existing township plan.
516053	Official restoration surveys affecting sections 1-6 may not have been incorporated into existing township plan.
516054	Official restoration surveys affecting sections 31-35 may not have been incorporated into existing township plan.
516055	Official restoration surveys affecting sections 1-7, 11-14, 18, 19, 23, 24, 30, 31 may not have been incorporated into existing township plan.
516056	Official restoration surveys affecting sections 5-8, 10, 11, 14-23, 26-34 may not have been incorporated into existing township plan.
516057	Official restoration surveys affecting sections 3-6 may not have been incorporated into existing township plan.
516084	Official restoration surveys affecting sections 3-6 may not have been incorporated into existing township plan.
516085	Official restoration surveys affecting sections 3-6, 13, 18, 19, 24, 25, 30-36 may not have been incorporated into existing township plan.
516087	Official restoration surveys affecting sections 7, 18, 19, 30, 31 may not have been incorporated into existing township plan. Official restoration surveys restoring other monuments may not have been incorporated into existing township plan.



Location	Comment
516088	Official restoration surveys affecting sections 6, 7, 18, 19, 30, 31 may not have been incorporated into existing township plan. Official restoration surveys restoring other monuments may not have been incorporated into existing township plan.
517039	All unsurveyed theoretical road allowances are 99 feet wide.
517047	Township plans within existing or former forest reserve areas may not show all surveyed sections.
517051	Official restoration surveys affecting sections 9, 10, 15, 16, 20-22, 24-29, 32-36 may not have been incorporated into existing township plan.
517052	Official restoration surveys affecting sections 4-9, 16, 17, 20, 21, 28, 29 may not have been incorporated into existing township plan.
517055	Official restoration surveys affecting sections 1, 7, 12, 13, 18, 24, 25, 36 may not have been incorporated into existing township plan.
517056	Official restoration surveys affecting sections 12, 13, 24, 25, 36 may not have been incorporated into existing township plan.
517057	Official restoration surveys affecting sections 7, 10, 11, 14, 15, 18, 19-23, 26-33 may not have been incorporated into existing township plan.
517071	Possible descriptive problem with the witness monument at E 1/4 18.
517084	Official restoration surveys affecting sections 31-36 may not have been incorporated into existing township plan.
517085	Official restoration surveys affecting sections 1-6,13, 24, 25, 31-34, 36 may not have been incorporated into existing township plan.
517086	Official restoration surveys affecting sections 1, 3-19, 23-26, 30, 31, 33-36 may not have been incorporated into existing township plan.
517087	Official restoration surveys affecting sections 1-4, 6, 12, 13, 24, 25, 36 may not have been incorporated into existing township plan.
517088	Official restoration surveys affecting sections 1, 12, 13, 24, 25, 36 may not have been incorporated into existing township plan. Official restoration surveys restoring other monuments may not have been incorporated into existing township plan.
518055	Official restoration surveys affecting sections 4, 5, 7-31-36 may not have been incorporated into existing township plan.
518056	Official restoration surveys affecting sections 1-6, 8, 9, 16, 17, 20, 21, 28, 29, 31-34 may not have been incorporated into existing township plan.
518057	Official restoration surveys affecting sections 3-6, 12, 13, 24, 25, 36 may not have been incorporated into existing township plan.
518084	Official restoration surveys affecting sections 31-36 may not have been incorporated into existing township plan.
518085	Official restoration surveys affecting sections 1-6, 11-14, 23-26, 35, 36 may not have been incorporated into existing township plan.

Location	Comment
518086	Official restoration surveys affecting sections 1-14, 23-26, 35, 36 may not have been incorporated into existing township plan.
519055	Official restoration surveys affecting sections 12, 13, 24, 25, 36 may not have been incorporated into existing township plan.
519073	Official restoration surveys restoring some monuments between 1953 & 1962 may not have been incorporated into existing township plan.
519076	Official restoration surveys affecting sections 1-6, 8-21, 23, 24, 28-33 may not have been incorporated into existing township plan.
519077	Official restoration surveys affecting sections 4-6 may not have been incorporated into existing township plan.
520051	Township plans within existing or former forest reserve areas may not show all surveyed sections.
520076	Official restoration surveys affecting sections 1, 13, 24, 25, 36 may not have been incorporated into existing township plan.
520084	Official restoration surveys restoring some monuments between 1953 & 1962 may not have been incorporated into existing township plan.
520085	Official restoration surveys restoring some monuments between 1953 & 1962 may not have been incorporated into existing township plan.
520087	Official restoration surveys affecting sections 4-9, 16-20, 29-31 may not have been incorporated into existing township plan.
520091	Official restoration surveys restoring some monuments between 1953 & 1962 may not have been incorporated into existing township plan.
521068	Possible descriptive problem with the witness monument on north boundary of section 31.
521072	Official restoration surveys restoring some monuments between 1953 & 1962 may not have been incorporated into existing township plan.
521082	Area in section 3 may be incorrect.
521083	Possible descriptive problem with the witness monument at NE 8. Posts shown on wrong side of road allowance affecting sections 4-6 may be incorrect?
521087	Official restoration surveys affecting sections 1, 12, 13, 24, 25, 36 may not have been incorporated into existing township plan.
522067	Description of monuments affecting sections 1 may be incorrect. Distance affecting east boundary of section 18 may be incorrect.
522088	Official restoration surveys restoring some monuments between 1953 & 1962 may not have been incorporated into existing township plan.
523067	Letter on file regarding E 1/4 6.
523090	Official restoration surveys affecting sections 19 & 30 may not have been incorporated into existing township plan.
524047	All unsurveyed theoretical road allowances are 99 feet wide.
524050	Official restoration surveys restoring some monuments between 1953 & 1962 may not have been incorporated into existing township plan.

Location	Comment
524052	Official restoration surveys affecting sections 19, 30-32 may not have been incorporated into existing township plan.
524053	Official restoration surveys affecting sections 5 & 6 may not have been incorporated into existing township plan.
524089	Official restoration surveys affecting sections 31-36 may not have been incorporated into existing township plan.
524090	Official restoration surveys affecting sections 1-7, 10, 11, 14-26, 30, 31 may not have been incorporated into existing township plan.
525047	All unsurveyed theoretical road allowances are 99 feet wide.
525048	All unsurveyed theoretical road allowances are 99 feet wide.
525051	Official restoration surveys affecting sections 31 & 32 may not have been incorporated into existing township plan.
525052	Official restoration surveys affecting sections 5-7, 18-20, 25, 25, 29, 35, 36 may not have been incorporated into existing township plan.
525053	Official restoration surveys affecting sections 1 & 2 may not have been incorporated into existing township plan.
525082	Distance affecting section 20 may be incorrect.
525084	Bearing affecting north boundary of section 20 may be incorrect.
525090	Official restoration surveys affecting sections 1, 12, 13, 24, 25, 36 may not have been incorporated into existing township plan.
525102	Monument and distance affecting section 27 may be incorrect.
526050	Official restoration surveys affecting sections 6, 7, 18-21, 28, 29, 32, 33 may not have been incorporated into existing township plan.
526052	Official restoration surveys affecting sections 12, 13, 24 may not have been incorporated into existing township plan.
526084	Description of monuments affecting section 36 may be incorrect.
601106	Distance affecting east boundary of section 36 may be incorrect.
601125	Survey data may not be shown on official plan or may be incorrect.
601126	Survey data may not be shown on official plan or may be incorrect.
602073	Official restoration surveys affecting sections 13, 22-24, 26, 27 may not have been incorporated into existing township plan.
602074	Official restoration surveys affecting sections 13, 14, 23-26 may not have been incorporated into existing township plan.
602088	Distance and bearing affecting sections 31-36 may be incorrect.
602116	Description of monuments affecting sections 31-36 may be incorrect.
603071	Surveyed road in sections 32 - 34 should have been located along the blind line south of the noted sections. See registered plan 374BM.
603088	Distance and bearing affecting sections 31-36 may be incorrect.
603116	Description of monuments affecting sections 31-36 may be incorrect.
604088	Distance and bearing affecting sections 31-36 may be incorrect.
604116	Description of monuments affecting sections 31-36 may be incorrect.

Location	Comment
605088	Distance and bearing affecting sections 31-36 may be incorrect.
605116	Description of monuments affecting sections 31-36 may be incorrect.
606072	Description of monuments affecting sections 28, 29, 32, 33 may be incorrect.
606084	Possible descriptive problem with the witness monument at NE 36-T83-R7-W6M.
606088	Distance and bearing affecting sections 31-36 may be incorrect.
606116	Description of monuments affecting sections 31-36 may be incorrect.
607083	Possible descriptive problem with the witness monument at NE 36-T83-R7-W6M.
607084	Possible descriptive problem with the witness monument at NE 36-T83-R7-W6M.
607086	Possible descriptive problem with the witness monument at NE31-85-7-6.
607088	Distance and bearing affecting sections 31-36 may be incorrect.
607116	Description of monuments affecting sections 31-36 may be incorrect.
608088	Distance and bearing affecting sections 31-36 may be incorrect. Official restoration surveys affecting sections 18, 19, 30, 31 may not have been incorporated into existing township plan.
608116	Description of monuments affecting sections 31-36 may be incorrect.
609088	Official restoration surveys affecting sections 13, 24, 25, 31-36 may not have been incorporated into existing township plan.
609116	Description of monuments affecting sections 31-36 may be incorrect.
610088	Official restoration surveys restoring some monuments between 1953 & 1962 may not have been incorporated into existing township plan. Distance and bearing affecting sections 31-36 may be incorrect.
610116	Description of monuments affecting sections 31-36 may be incorrect.
611068	Posts shown on wrong side of road allowance affecting sections 31-36 may be incorrect.
611069	Posts shown on wrong side of road allowance affecting sections 1-6 may be incorrect.
611084	Official restoration surveys restoring some monuments between 1953 & 1962 may not have been incorporated into existing township plan.
611085	Official restoration surveys restoring some monuments between 1953 & 1962 may not have been incorporated into existing township plan.
611116	Description of monuments affecting sections 31-36 may be incorrect.
612084	Official restoration surveys restoring some monuments between 1953 & 1962 may not have been incorporated into existing township plan.
612085	Official restoration surveys restoring some monuments between 1953 & 1962 may not have been incorporated into existing township plan.
612088	Distance and bearing affecting sections 31-36 may be incorrect.
612116	Description of monuments affecting sections 31-36 may be incorrect.
613076	Possible descriptive problem with the witness monument at E 1/4 31. Discrepancies with adjoining township plan on north boundary.
613080	Letter on file regarding E 1/4 29.